

DEPARTMENT OF TRANSPORTATION**DIVISION OF ENGINEERING SERVICES**

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-001453**Date Inspected:** 20-Feb-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 1800**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 630**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** N/A**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** DP-014**Summary of Items Observed:**

On this date, Caltrans Office of Structural Materials (OSM), Quality Assurance (QA) Inspector, David A. Smith was present for the observations related the following;

Bay-1, A visual weld inspection was performed by this Caltrans QA Inspector on the 8 welds that make up the Deck Plate Assembly DP-014. Discrepancies observed were Undercut, Excess Weld Buildup, Overlap and Lack of Fusion. The lengths and the location of each of these areas were listed in the Caltrans QA Visual Weld Inspection Report for the OBG Deck Panel. Copies of these reports were left for Jimmy Cochran and Alfredo Acuna for their review.



1900 02 20 2008



1900 02 20 2008

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Summary of Conversations:

There were no pertinent conversations pertaining to the project during this shift.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Smith,David	Quality Assurance Inspector
----------------------	-------------	-----------------------------

Reviewed By:	Cochran,Jim	QA Reviewer
---------------------	-------------	-------------